General Environmental Incident Summary

Incident: 3692 Date/Time Notice: 3/22/2015 0730 DEM Incident No:

Responsible Party: Schlumberger

Date Incident: 3/22/2015 Time Incident: 0700 Duration: 1 hours

 County:
 Dunn
 Twp:
 144
 Rng:
 95
 Sec:
 17
 Qtr:

 Lat:
 47.28687
 Long:
 -102.75750
 Method:
 Interpolation from map

Location Description: ND 22 Northbound approximately 6 miles south of Killdeer ND.

Submitted By: Terence Furlong Affiliation: Schlumberger

Address: 190 26th Street East

City: Dickinson State: ND Zip: 58601

Received By:

Contact Person: Terence Furlong

190 26th Street East Dickinson, ND 58601

Distance Nearest Occupied Building: Release Contained: No

Type of Incident: Vehicle Accident

Description of Released Contaminant: Diesel fuel oil no 2

Volume Spilled: 125.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Icy road conditions vehicle rolled on to driver side causing diesel to spill on to sholder

Risk Evaluation:

No free standing liquids, in open air flash point out is below LEL

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:Potential absorption to 4-6 yards of soil

Action Taken or Planned:

Contacted Mirror Image Environmental Services for area survey and remediation 20150322 1013

Wastes Disposal Location: TBD

Agencies Involved: NDDES, Local Law Enforcement

Updates

Date: 3/22/2015 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Volume:

Notes:

Vehicle accident on Hwy 22 south of Killdeer. Diesel fuel spill. Followup is necessary.

Date: 3/25/2015 Status: Inspection Author: Crowdus, Kory

Updated Volume:

Notes:

At location 3/25/15, at 12:05 p.m. Release was to the east side of road and ditch. Area is marked by cones, and a 10- X 10-foot area has been excavated to a depth of 3-4 feet. Soil is being placed in metal containers at location. No remaining impact seen at this time.